CIBLE LAKE CARMEL

WELL COMPLETION REPORT 3/71

41 24 29 73 44 59

## PUTNAM COUNTY DEPARTMENT OF HEALTH

Division of Environmental Health Services
COUNTY OFFICE BUILDING - CARMEL, NEW YORK

This report is to be completed by well driller and submitted to County Health Department together with laboratory report of analysis of water sample indicating water is of satisfactory bacterial quality before certificate of construction compliance is issued.

	NAME				ADDRESS				
OWNER	Donald Hill			Long Pond Rd., Mahopac, NY					
OF WELL			(No. & Street)	lahopac,		(Tawn)	720120	(Lot No	mber)
PROPOSED USE OF WELL	PROPOSED DOMESTIC		BUSINESS ESTABLISHMENT INDUSTRIAL		FARM  AIR CONDITIONING		TEST WELL  OTHER 625 N (Specify)		
DRILLING EQUIPMENT X ROTARY		COMPRESSED AIR PERCUSSION		CABLE	CABLE PERCUSSION		OTHER (Specify)		
CASING DETAILS		H (feet)	DIAMETER (inches)			METDED	DRIVE SHOE	WAS CASING GE	NO NO
YIELD TEST		AILED	X PUMPED	COMPRESS		Hours 6	G.≱.M. 8	YIELD (G.P.M.)	72445
(0.00) 0.00 (1.00)		O ft.	FROM LAND SURFACE-STATIC(Specify feet) DURING ft.			201	Depth of Completed Well in feet below Land surface: 1 50 f		ı
SCREEN	MAKE							LENGTH OPEN TO	AQUIFER (test)
DETAILS	SLOT SIZE		DIAMETER (Inches)	IF GRAVEL PACKED:	Diameter of w gravel pack ()		GRAYEL SIZE (Inches)	FROM (feet) TO (feet)	
PEET to PE	_		FORMATION DESCR	IPTION		Sketch exect two permaner	location of well with di t landmarks.	stances, to at least	- 11
8 2 2 2 1	50 Drilling in rock-granite &				& Quartz	ite			
DATE WELL COMPLE	ETED	DATE OF 8/22/	REPORT WELL	DRILLEA (Sign	nature) ),	1. 0	T. 15	7-	